


1. Mount OPTALIGN® V

Press **ON/OFF** and press **/** (for inch mode)



NOTE: Use inclinometers on both shafts if there is coupling backlash or when aligning uncoupled.

Important Note: The serial numbers of the Laser (Transducer) and Computer must match on an Optalign® V to have an accurate system!


LUDECA Inc.
 1425 N.W. 88th Avenue
 Miami, FL 33172
 www.ludeca.com
 Phone: (305) 591-8935
 Fax: (305) 591-1537
 eMail: info@ludeca.com



Productive maintenance technology

2. Enter dimensions

Press **ENT** or press **DIM**




- 1 **ENT** Laser to prism
- 2 **ENT** Laser to MTBM front foot*
- 3 **ENT** Front foot to back foot
- 4 **ENT** Coupling center to prism
- 5 **ENT** Coupling diameter

*Use laser sidebeam to assist measurement. Fractions of an inch can be entered using the slash e.g. 9.75" can be keyed in as 9 3 / 4

3. Measure

- a) Press **M**, use red dust caps to track beam. Adjust prism along posts and with thumbscrew until 0 0 displayed.
- b) Measure in at least three of the four quarter-hour clock positions, as viewed towards the stationary machine:



4. Coupling misalignment

Press **VA** . **ENT** cycles through vertical and horizontal offset and angular misalignment.

A positive offset means MTBM is higher or towards 3 o'clock.


Angular misalignment is in terms of the gap size. Positive means open above or towards 3 o'clock.



If values are within required tolerances then the machines are aligned!

5. Foot corrections

Press **VA** . **ENT** cycles through vertical shimming, then horizontal move corrections.



Shim feet to the vertical values. Repeat measurements (see 3.) before proceeding to horizontal move.

6. Horizontal move

- a) Press **VA** and turn shafts to 1:30 o'clock position, press **ENT**.
- b) Adjust prism to display 0 0, press **ENT**.
- c) Move each highlighted foot until both front and back are aligned.

For very large horizontal corrections adjust horizontally before shimming.

OPTALIGN® V selected special functions

Soft Foot

- Press and rotate shaft to 3 or 9 o'clock.
- Adjust prism until 0 0 displayed and press .
- Unbolt the displayed foot, record movement, retighten; press and repeat with the next foot.
- The results must be carefully analyzed to determine the correct shimming. See examples in the manual.

Extend measurement range

If END or OFF appear during rotation,

- turn shaft back until numbers just reappear. Press .
- Keeping shaft steady, re-zero prism.
- Press again and continue with measurements.

This function can be used similarly with MOVE (part 6.)

Target alignment at coupling

Press , enter offset and gap target values for MTBM, following sign conventions in 4. overleaf.

Continuously rotating shafts

Semi-automatic measurement with just one keypress in each clock position.
F2 = Clockwise, F3 = Anti-clockwise

Press and chosen start position e.g.

Press as shaft rotates past start position, and again at each subsequent clock position.


Thermal growth at machine feet

Press F4 and enter expected MTBM foot growths. 12 and 3 o'clock are positive.

Vertical machine (see manual)

90° restricted shaft rotation

If normal clock positions are not possible, press F6 to display . Measure at 10:30, 12:00 and 1:30, but entered with the 9, 0 and 3 keys, thus:



2 coupling plane offsets (see manual)

Alignment tolerances

- Press F8 and enter RPM (from 1 to 7200), press .
- If alignment is within tolerance 'o.k' flashes otherwise computer beeps twice.

Storing and Printing


Stores up to 5 sets of data.

Prints first set of stored data. prints next set.

Transfers all stored data to a PC.

OPTALIGN® V

Short Instructions



Voelzow & Company, Inc.

P.O. Box 158 • Wingate, NC 28174
704-233-9222 • Fax 704-233-9211
E-mail: voelzow@perigee.net
Web: www.LaserAlignment.net