




Plant	XYZ Processing Plant
Thermographer	Frank Rizzo
Date	5/2/2003
Time	9:49:42 AM

Component	Three Phase Fuse
Location	Area 11



Thermal Image Data	
Reference avg temp	40.6 ° C
Hot Spot max temp	55.9 ° C
Temperature Rise	17.2° C
Classification	B

Classification Table		
A	<10°C	Monitor
B	10-20°C	Repair in one year
C	20-30°C	Repair Next Outage
D	>30°C	Repair Immediately

Result Table					
ITEM	TYPE	AVG TEMP	MAX TEMP	MIN TEMP	
Whole Image	Image	39.2	57.8	32.6	
Hot Spot	Area	52.7	55.9	46.7	
Reference	Area	40.6	41.7	39.5	

This Report Generated by **Electrophysics ReportIR** Report Writing Package
 All Thermographic Images Taken With an **Electrophysics EZ Therm** Camera